

Summary of Facility Information in the County of Musselshell

Owner Name and Address: Jakes Garage 221 US Highway 12 Melstone MT 59054 Phone: (406) 358-2389

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3301481	Jakes Garage	221 US Highway 12	Melstone	59054	(406) 358-2389

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
8 / 08 Currently In Use	3770	12/1/1998 07 / No	Gasoline 3,750	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Safe Suction	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes
9 / 09 Currently In Use	3771	12/1/1998 07 / No	Gasoline 2,250	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	U.S. Suction	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Musselshell

Owner Name and Address: McCleary Distributing Inc PO Box 406 Roundup MT 59072 Phone: (406) 323-1108

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3301083	Main Street Texaco	304 Main St	Roundup	59072	(406) 323-3646

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
7 / 07 Currently in Use	1588	11/20/1990 15 / No	Gasoline 3,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C D <input checked="" type="radio"/> F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
8 / 08 Currently in Use	1589	11/20/1990 15 / No	Gasoline 3,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C D <input checked="" type="radio"/> F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
9 / 09 Currently in Use	1590	11/20/1990 15 / No	Gasoline 3,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C D <input checked="" type="radio"/> F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Musselshell

Owner Name and Address: Wells Fargo Bank 12 Main St Roundup MT 59072 Phone: (406) 323-2000

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3302079	Wells Fargo Bank Roundup	12 Main St	Roundup	59072	(406) 323-2000

TankID/Alt TankID	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
1 / S2 Currently in Use	3495	10/6/1993 12 / No	Heating Oil 2,000	STI-P3 Double-Walled	Copper Double-Walled/Non-Corro	Safe Suction	<div> <div>A B C D E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div>	<div> <div>A B C D E F <input checked="" type="radio"/> H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Musselshell

Owner Name and Address: McCleary Distributing Inc PO Box 406 Roundup MT 59072 Phone: (406) 323-1108

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3305030	Conoco Convenience Center	806 Main St	Roundup	59072	(406) 323-1108

TankID/Alt TankID	Tag Numbe	Installed	Product	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status		Age/AST	Capacity	Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
1 / 09 Currently in Use	1594	10/1/1996 09 / No	Diesel 4,000	STI-P3 Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr></table>	A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B		D	E	F	<input checked="" type="radio"/>	H	I	J	K	L		Yes Yes Yes Yes
A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B		D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																						
2 / 07 Currently in Use	1592	8/30/1989 16 / No	Gasoline 4,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L			Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																							
3 / 08 Currently in Use	1593	9/1/1992 13 / No	Gasoline 4,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L			Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																							
4 / 06 Currently in Use	1591	8/30/1989 16 / No	Gasoline 4,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L			Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																							
10 / 10 Currently in Use	1595	10/1/1996 09 / No	Diesel 2,000	STI-P3 Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr></table>	A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B		D	E	F	<input checked="" type="radio"/>	H	I	J	K	L		Yes Yes Yes Yes
A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B		D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																						
11 / 11 Currently in Use	1596	10/1/1996 09 / No	Diesel 4,000	STI-P3 Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr></table>	A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B		D	E	F	<input checked="" type="radio"/>	H	I	J	K	L		Yes Yes Yes Yes
A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B		D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																						
12 / 12 Currently in Use	1597	10/1/1996 09 / No	Diesel 2,000	STI-P3 Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr></table>	A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B		D	E	F	<input checked="" type="radio"/>	H	I	J	K	L		Yes Yes Yes Yes
A	B	C	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B		D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																						

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Musselshell

Owner Name and Address: Stockton Oil Co 1607 4th Ave N PO Box 1756 Billings MT 59103 Phone: (406) 245-6376

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3306612	Express Center Convenience Store	701 1st Ave W	Roundup	59072	(406) 323-1171

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	3757	3/26/1985 21 / No	Gasoline 10,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C ● E F G H I J K L</div> <div>● ● E F G H I J K L</div> </div>	Yes Yes Yes Yes
2 / 02 Currently in Use	3758	3/26/1985 21 / No	Gasoline 8,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C ● E F G H I J K L</div> <div>● ● E F G H I J K L</div> </div>	Yes Yes Yes Yes
3 / 03 Currently in Use	3759	3/26/1985 21 / No	Gasoline 4,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C ● E F G H I J K L</div> <div>● ● E F G H I J K L</div> </div>	Yes Yes Yes Yes
4 / 04 Currently In Use	1985	10/1/1998 07 / No	Diesel 8,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<div> <div>A B C ● E F G H I J K L</div> <div>B D E F ● H I J K L</div> </div>	Yes Yes Yes Yes
5 / 05 Currently In Use	1986	10/1/1998 07 / No	Diesel 5,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<div> <div>A B C ● E F G H I J K L</div> <div>B D E F ● H I J K L</div> </div>	Yes Yes Yes Yes
6 / 06 Currently In Use	1987	10/1/1998 07 / No	Diesel 4,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<div> <div>A B C ● E F G H I J K L</div> <div>B D E F ● H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed